

Air Conditioning Evaporator Condensate Drain

If your XM has Air Conditioning and the carpet gets wet in the front footwells, it may be the condensate drain from the evaporator section. As the evaporator cools the air condensation forms on the fins and dribbles down into the collection tray at the bottom. A plastic tube connects on to the outlet pipe as shown and leads the water away out of the car. It is possible for the tube to become disconnected from the spigot.

You can see the whole heater unit viewed from the offside (RH Drive) here:

